



For Immediate Release  
September 2, 2015

Maribel Lena, 305-470-5349  
[maribel.lena@dot.state.fl.us](mailto:maribel.lena@dot.state.fl.us)

---

## **UPDATE: Closure of State Road (SR) 836 Ramp to Southbound SR 826 and West Flagler Street**

---

**Miami, FL** – The eastbound SR 836 ramp and flyover bridge to West Flagler Street/southbound SR 826 will be closed on Thursday, September 3, between the hours of 9 p.m. and midnight.

**Drivers on the eastbound SR 836 ramp to West Flagler Street/southbound SR 826 can:**

- Continue east on SR 836, exit at NW 72 Avenue/Milam Dairy Road
- South on NW 72 Avenue/Milam Dairy Road
- West on West Flagler Street to connect with the southbound SR 826 ramp

**Drivers on the eastbound SR 836 flyover bridge to southbound SR 826 can:**

- Take the flyover bridge to northbound SR 826, exit at NW 25 Street
- Go west on NW 25 Street, to access the southbound SR 826 ramp

The closures will allow the contractor to place bridge beam adjacent to the roadway. **Please note that this schedule may change due to bad weather or other unforeseen conditions.**

For more information about the SR 826/SR 836 Interchange Reconstruction Project, please contact Construction Public Information Specialist Oscar Gonzalez at 786-280-0983 or Project Engineer Francis Chin at 305-388-5450 or go to [www.826-836.com](http://www.826-836.com).

Drivers are encouraged to call 511 before they drive or log on to [www.fl511.com](http://www.fl511.com) to get real-time traffic and lane closure information. FDOT reminds drivers that wearing a safety belt is the single most effective way to protect people and reduce fatalities in motor vehicle crashes. Please drive cautiously in work zones.

**Celebrating 100 Years of Innovation, Mobility and Economic Development**

---

[www.dot.state.fl.us/agencyresources/anniversary/](http://www.dot.state.fl.us/agencyresources/anniversary/)  
FDOTMiamiDade.com | @MyFDOT\_Miami | Facebook.com/MyFDOTMiami