



# Structural and Functional Deficiencies

Bridge No.	DOT Bridge No.	NBI Condition Rating							
		Sufficiency Rating							Deficiency FO/SD
		2011	2012	2013	2014	2015	2016	2017*	2017
1	874459	32.6	32.6	32.6	19	-	-	64.0	-
2	874460	52.0	52.0	54.7	45.9	45.9	45.9	49.9	FO
3	874461	55.5	55.5	52.2	46.0	46.0	36.5	41.3	FO
4	874463	55.5	55.5	55.3	46.0	46.0	36.5	41.3	FO
5	874465	47.9	47.9	47.6	36.5	36.5	36.5	41.3	FO
6	874466	57.6	57.6	54.4	48.2	48.2	39.2	43.8	FO
7	874471	55.5	49.9	52.2	46.0	46.0	46.0	41.3	FO
8	874472	55.5	55.5	55.5	46.0	46.0	36.5	41.3	FO
9	874473	64.0	64.0	61.0	48.7	48.7	48.7	44.3	FO
10	874474	57.5	54.5	54.5	32.1	32.1	32.1	32.2	FO
11	874477	64.0	64.0	56.7	41.0	41.0	30.0	35.6	FO
12	874481	68.1	68.1	68.1	40.4	40.4	40.4	34.9	FO

\* Based on FDOT Bridge Information. April 3rd 2017

FO = Functionally Obsolete SD = Structurally Deficient